


Turbina Nuova Aftermarket Land-Rover Discovery II 2.5 TD5 Build : from Jan 2002



Land-Rover Discovery II 2.5 TD5 Engine: MDI 525 Capacity: 2496 ccm Power: 90 Kw - 122 HP Build: from Jan.2002 Part Number/s 452239-5009S 452239-5008S 452239-0009 452239-0006 452239-0005 452239-0003 Comparison Number/s LR017316 LR006595 LR005955 PMF50040 PMF100460 PMF100410 PMF000040

Valutazione: Nessuna valutazione

Prezzo

Prezzo di vendita 351,36 €

[Fai una domanda su questo prodotto](#)

Descrizione

TURBO NUOVO AFTERMARKET

Recensioni

Nessuna recensione disponibile per questo prodotto.